



Friday, January 12th 2018

Esplanada HOA Members at Boca Pointe
Boca Raton, FL 33433
[P] 561.400.1880
[E] rabobfl@gmail.com

**RE: CONSTRUCTION COMPLETION CERTIFICATION
LAKE #3 SHORLINE SLOPE ADJUSTMENT**

Mr. Robert Golden – Homeowner's Association President:


This letter shall serve as the ***Engineer's Letter of Certification*** for the above-referenced Lake #3 Project. Overall, the work was conducted by the general contractor, LAKE AND WETLAND MANAGEMENT, INC., and was found to have completed all items and tasks as described in the contract as well as the post factum punch list provided by CRJ & Associates, Inc.

In our professional review, and to the best of our abilities through regular field observations and inspections, the work product conforms to the Esplanada HOA Members' objectives and specifications as laid out in the contract and has been deemed complete.

Should there be any need to communicate to me directly, please feel free to call me at (954) 650-5335 (cell) or at my office headquarters (954) 239-4330. Thank you for your time.

Sincerely,
CRJ & ASSOCIATES, INC.

Marc A. Fermanian, P.E. – President
Florida Lic. No. 52626





Aerial Image of Work (12/12/2017): Demonstration of Work Area conducted for the day's Inspection



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Aerial
Image



1 - (12/12/2017): Overview of Lake #3 from the southwest corner. Amphibious dredger in the background working on east shoreline.



2 - (12/12/2017): East side of lake facing north. Photograph taken at today's "starting point" of membrane fill. NOTE: Work did not start until +/- 1:15pm due to equipment issues.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



3 - (12/12/2017): East side of Lake #3 where work was conducted in filling dredged soils into membrane (i.e., Dredgesox™); photo taken facing northward.



4 - (12/12/2017): East side of Lake #3 where work was conducted in filling dredged soils into membrane (i.e., Dredgesox™); photograph taken facing southward.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



5 - (12/12/2017): Lake & Wetland Management, Inc. utilized small bale(s) of pine needles (yellow arrows) used as part of membrane fill in proximity of PVC lines to minimize washout during dredging soils installation.



6 - (12/12/2017): Amphibious dredger moved northward along the eastern shoreline of Lake #3 to continue installation of in-situ soils materials within membrane.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



Aerial Image of Work (12/11/2017): Demonstration of Work Area conducted for the day's Inspection



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Aerial
Image



1 - (1/11/2018): Facing south, away from the lake, showing the re-sodded entrance completed.



2 - (1/11/2018): Facing north from the south west corner of the lake.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



3 - (1/11/2018): Facing east from the south west corner of the lake.



4 - (1/11/2018): Facing north from the south east corner of the lake.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



5 - (1/11/2018): Facing west from the south east corner of the lake.



6 - (1/11/2018): Facing north west from the eastern bank, showing the northern bank of the lake.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



7 - (1/11/2018): Facing south from the north east corner of the lake.



8 - (1/11/2018): Facing east along the north bank from the north west corner of the lake.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos



9 - (1/11/2018): Facing south from the north west corner of the lake.



10 - (1/11/2018): Facing south along the eastern bank of the lake.



CRJ & Associates, Inc.
Consulting Engineers and Planners

Property: Boca Pointe – Esplanada HOA
Location: Esplanada – Lake #3
Client: Esplanada HOA (Robert Golden, President HOA)
Job No: BOC-1000

Site
Photos